

# Autofocus Video Inspection Probe G0382A

### What is Video Inspection Probe?

Scratches and stains to optic fiber ferrule endfaces are often said to have a negative impact on transmission quality.

The Video Inspection Probe can be connected to several Anritsu products as well as Windows® PCs, to show the state of a ferrule endface.


This function is effective for determining whether a ferrule endface is clean, and whether connector replacement is necessary due to connector scratches.







### Connector Endface is Dirty/Damaged...


When a connector endface is dirty, it tends to produce a greater amount of reflection. A good connection can be maintained by cleaning connector endfaces. When a connector endface is damaged, in addition to having a greater amount of reflection, it also tends to exhibit greater splice loss. When the amount of reflection or loss caused by the damage is high, the connector port needs to be replaced.





#### <Case of OTDR Trace situation>








#### G0382A Autofocus Video Inspection Probe Overview

## **Key Features**

- Highest speed measurement with fully Automated one-button operation
  - ✓ Automated focus
  - ✓ Automated image centering
  - ✓ Automated analysis
  - ✓ Automated image capture
- Easy to read LED indicator displaying status
- Compact and light weight
- Wide range of adaptors available





\*Photo is connected to MT1000A



### **Supported Products**

#### MT1000A/MT1100A Series





Include Pass/Fail analysis function (Software version 7.05 or later)

Windows PC with MX900031A Autofocus VIP Software



Include Pass/Fail analysis function (New Software for G0382A)

#### G0382A Tips



Tips are connected to the end of the VIP based on the shape of connector (adapter) to be connected.

This unit comes standard with 7 types of tips.



1.25mm PC Male



2.5mm PC Male



2.5mm APC Male



1.25mm PC Female(LC)



2.5mm PC Female(FC)



2.5mm PC Female(SC)



2.5mm APC Female(SC)



### **Examples of Tip Connection**





#### ●Tips for bulk head type

As this figure shows, the ferrule endface of the connected fiber can be checked via this bulk type adapter.







#### Tips for universal patch cord type

As this figure shows, the universal type tip can be used to directly plug into the ferrule for test.

## Fully automated one-button operation (1/3)



### Fully automated one-button operation (2/3)



Green: Pass Red: Fail

**Blue: Active** 

Moreover, supported onboard Pass/Fail LED indicator

Auto

File Save

From the Table View, you can

on the end of the fiber.

(1) Defects in each area.

(2) Scratches in each area.(3) Overall determination for

each area merging (1) and (2)

identify "defects" or "scratches"

\*H0392A MPO tip does not have Autofocus and Pass/Fail functions.


The automatic pass/fail determination is made in accordance with the IEC61300-3-35 standard.

Zone	Dia.(µm)	Defects	Defect Count	Area (μm²)	Scratch	Scratch Count
Core	25	PASS	0	0.00	PASS	0
Cladding	120	PASS	0	0.00	PASS	0
Adhesive	130	PASS	0	0.00	PASS	0
Contact	250	PASS	0	0.00	PASS	0




Pass


## Fully automated one-button operation (3/3)



#### **Saving the Measurement Results**

Support File format		MT1000A/MT1100A		MX900031A on Windows PC	
		File Support	Auto Save	File Support	Auto Save
Save to File	Data file (.vipi)	✓	<b>√</b>	NA	N/A
	Image file (png.)	✓	<b>√</b>	NA	N/A
	Report file	√ (PDF)	NA	✓ (Excel)	1
Load from File	Data file (.vipi)	<b>√</b>		NA	
	Image file (png.)	<b>√</b>		NA	
	Report file	✓ (PDF) On PDF Viewer		NA	





Excel Report (MX900031A)



## Ordering Information (1/2)

Model No.							
G0382A		Autofocus Video Inspection Probe					
- Standard accessories*1 -		Soft Bag Seven Connector Tips - 1.25mm PC Male, - 2.5mm PC Male, - 2.5mm APC Male, - 1.25mm PC Female(LC), - 2.5mm PC Female(FC), - 2.5mm PC Female(SC), - 2.5mm APC Female(SC) Quick Reference Guide					
		Арр	lication Parts				
Model No.							
H0382A	2.5PC-M (2.5mm PC Male)		H0395A	FC-APC-F (FC APC Female)			
H0383A	1.25PC-M (1.25mm PC Male)		H0385A	LC-PC-F (LC PC Female)			
H0387A	2.5APC-M (2.5mm APC Male)		H0393A	LC-PC-F-L (LC PC Long Female)			
H0388A	1.25APC-M (1.25mm APC Male)		H0394A	LC-APC-F-L (LC APC Long Female)			
H0384A	SC-PC-F (SC PC Female)		H0396A	ST-PC-F (ST PC Female)			
H0398A	SC-APC-F (SC APC Female)		H0397A	MU-PC-F (MU PC Female)			
H0386A	FC-PC-F (SC	PC Female)	H0390A	E2000-PC-F (E2000 PC Female)			
			H0392A*2	MPO-PC/APC-F (MPO PC/APC Female)			

<sup>\*1:</sup> Operation manual and MX900031A Autofocus VIP Software (For PC) can be downloaded from Anritsu public Web site.

#### G0382A Supported...

- MT1000A Network Master Pro, MT1100A Network Master Flex.
- Windows 7, 8 and 10 supported with MX900031A Autofocus VIP Software.



<sup>\*2:</sup> H0392A MPO tip does not have Autofocus and Pass/Fail functions.


### Ordering Information (2/2)

#### **G0382A Video Inspection Probe and Standard Accessories**

- (1) Standard Soft case
- (2) Video Inspection Probe
- (3) Tip for measurement
- (4) Quick Reference Guide
- (5) Standard Tips









#### Web Download Items

- (6) Operation manual
- (7) MX900031A Autofocus VIP Software (For PC)
- \* The files will be able to download from Anritsu public Web site.



#### **Anritsu VIP Series**

Mainframe	G0382A (Fixed x400 USB Autofocus VIP type)		G0306B (Fixed x400 USB Standard VIP type)				
	Firmware version:	Pass/Fail	Firmware version:	Pass/Fail			
MT1x00 Network Master Series							
MT1000A Network Master Pro.	Ver.7.05 or later	<b>✓</b>	Ver.5.00 or later	<b>V</b>			
MT1100A Network Master Flex	Ver.7.05 or later	<b>✓</b>	Ver.5.00 or later	V			
MT9090A Network Master							
MU909014x/15x (μOTDR)	NA		Ver.2.27 or later	<b>V</b>			
ACCESS Master Series							
MT9083x2 Series ACCESS Master	NA		Ver.2.02 or later	V			
Others							
MX900031A with Autofocus VIP Software (For PC) *1	Ver.1.00 or later		NA				
MX900030A with Connector Master (For PC) *2	NA		Ver.1.02 or later	V			

<sup>\*1:</sup> PC analysis software for G0382A (Support Windows XP, Windows 7, Windows 8 and Windows 10). The MX900031A available from the Anritsu public web site.

The MX900030A available from the Anritsu public web site.



<sup>\*2:</sup> PC analysis software for G0306B (Support Windows XP, Windows 7 (32bit, 64bit), and Windows8 (32bit, 64bit).

